

## dsPIC33F Rev. A2 Silicon Errata

### dsPIC33FJXXXGPXXX, dsPIC33FJXXXMCXXX (Rev. A2) Silicon Errata

The dsPIC33F devices (Rev. A2) you received were found to conform to the specifications and functionality described in the following documents:

- DS70165 – “*dsPIC33F Family Data Sheet*”
- DS70157 – “*dsPIC30F/33F Programmer’s Reference Manual*”
- DS70046 – “*dsPIC30F Family Reference Manual*”

The exceptions to the specifications in the documents listed above are described in this section. The specific devices for which these exceptions are described are listed below:

- dsPIC33FJ64GP206
- dsPIC33FJ64GP306
- dsPIC33FJ64GP310
- dsPIC33FJ64GP706
- dsPIC33FJ64GP708
- dsPIC33FJ64GP710
- dsPIC33FJ128GP206
- dsPIC33FJ128GP306
- dsPIC33FJ128GP310
- dsPIC33FJ128GP706
- dsPIC33FJ128GP708
- dsPIC33FJ128GP710
- dsPIC33FJ256GP506
- dsPIC33FJ256GP510
- dsPIC33FJ256GP710
- dsPIC33FJ64MC506
- dsPIC33FJ64MC508
- dsPIC33FJ64MC510
- dsPIC33FJ64MC706
- dsPIC33FJ64MC710
- dsPIC33FJ128MC506
- dsPIC33FJ128MC510
- dsPIC33FJ128MC706
- dsPIC33FJ128MC708
- dsPIC33FJ128MC710
- dsPIC33FJ256MC510
- dsPIC33FJ256MC710

dsPIC33F Rev. A2 silicon is identified by performing a “Reset and Connect” operation to the device using MPLAB® ICD 2 with MPLAB IDE v7.40 or later. The output window will show a successful connection to the device specified in Configure>Select Device.

The errata described in this section will be addressed in future revisions of silicon.

### Silicon Errata Summary

The following list summarizes the errata described in further detail through the remainder of this document:

1. Doze Mode  
When Doze mode is enabled, any writes to a peripheral SFR can cause other updates to that register to cease to function for the duration of the current CPU clock cycle.
2. 12-bit Analog-to-Digital Converter (ADC) Module  
For this revision of silicon, the 12-bit ADC module INL, DNL and signal acquisition time parameters are not within the published data sheet specifications.
3. 10-bit ADC Module  
For this revision of silicon, the 10-bit ADC module DNL, conversion speed and signal acquisition time parameters are not within the published data sheet specifications.
4. DMA Module: Interaction with EXCH Instruction  
The EXCH instruction does not execute correctly when one of the operands contains a value equal to the address of the DMAC SFRs.
5. DISI Instruction  
The DISI instruction will not disable interrupts if a DISI instruction is executed in the same instruction cycle that the DISI counter decrements to zero.
6. Motor Control PWM  
There is a glitch in the PWMxL signal in Single-Shot mode with complementary output. Another glitch occurs when resuming from a Fault condition in Free-Running mode with complementary output.

## 7. Output Compare Module

The output compare module will produce a glitch on the output when an I/O pin is initially set high and the module is configured to drive the pin low at a specified time.

## 8. Output Compare Module in PWM Mode

The output compare module will miss one compare event when the duty cycle register value is updated from 0x0000 to 0x0001.

## 9. SPI Module in Frame Master Mode

The SPI module will fail to generate frame synchronization pulses in Frame Master mode.

## 10. SPI Module in Slave Select Mode

The SPI module Slave Select functionality will not work correctly.

## 11. SPI Module

The SMP bit does not have any effect when the SPI module is configured for a 1:1 prescale factor in Master mode.

## 12. ECAN™ Module

ECAN transmissions may be incorrect if multiple transmit buffers are simultaneously queued for transmission.

## 13. ECAN Module

Under specific conditions, the first five bits of a transmitted identifier may not match the value in the transmit buffer ID register.

## 14. ECAN Module Loopback Mode

The ECAN module (ECAN1 or ECAN2) does not function correctly in Loopback mode.

## 15. I<sup>2</sup>C™ Module

The bus collision status bit does not get set when a bus collision occurs during a Restart or Stop event.

## 16. INT0, ADC and Sleep/Idle Mode

ADC event triggers from the INT0 pin will not wake-up the device from Sleep or Idle mode if the SMPI bits are non-zero.

## 17. Doze Mode and Traps

The address error trap, stack error trap, math error trap and DMA error trap will not wake-up a device from Doze mode.

## 18. JTAG Programming

JTAG programming does not work.

The following sections will describe the errata and work around to these errata, where they may apply.

## 1. Module: Oscillator: Doze Mode

Enabling Doze mode slows down the CPU but allows peripherals to run at full speed. When the CPU clock is slowed down by enabling Doze mode ( $\text{CLKDIV}<11> = 1$ ), any writes to a peripheral SFR can cause other updates to that register to cease to function for the duration of the current CPU clock cycle. This is only an issue if the CPU attempts to write to the same register as a peripheral while in Doze mode.

For instance, if the ADC module is active and Doze mode is enabled, the main program should avoid writing to ADCCONx registers because these registers are being used by the ADC module. If the CPU does make writes before the ADC module does, then any attempts by the ADC module to write to these registers will fail.

### Work around

In Doze mode, avoid writing code that will modify SFRs which may be written to by enabled peripherals.

## 2. Module: 12-bit ADC

When the ADC module is configured for 12-bit operation, the specifications in the data sheets are not met.

### Work around

Implement the ADC module as an 11-bit ADC with a maximum conversion rate of 300 Ksps.

1. The specifications provided below reflect 11-bit ADC operation. RIN source impedance is recommended as 200 ohms and sample time is recommended as 3 TAD to ensure compatibility on future enhanced ADC modules. Missing codes are possible every  $2^7$  codes.
2. When used as a 10-bit ADC, the INL is  $<\pm 2$  LSBs, and DNL is  $<\pm 1$  LSB with no missing codes. Maximum conversion rate is 300 Ksps.

**TABLE 1: ADC PERFORMANCE (11-BIT OPERATION)**

Param No.	Symbol	Min	Typical	Max	Units	Conditions
AD17	RIN	—	—	200	Ohm	12-bit
<b>ADC Accuracy – Measurements taken with External VREF+/VREF-</b>						
AD20a	Nr	—	12 bits	—	Bits	
AD21a	INL	-2	—	2	LSB	
AD22a	DNL	-1.5	—	1	LSB	
AD23a	GERR	1	5	10	LSB	
AD24a	EOFF	1	3	6	LSB	
<b>ADC Accuracy – Measurements taken with Internal VREF+/VREF-</b>						
AD21aa	INL	-2	—	2	LSB	
AD22aa	DNL	-1.5	—	1	LSB	
AD23aa	GERR	5	10	20	LSB	
AD24aa	EOFF	3	6	15	LSB	
<b>Dynamic Performance</b>						
AD33a	FNYQ	—	—	150	KHz	
AD34a	ENOB	9.5	9.6	10.4	Bits	
<b>ADC Conversion Rate</b>						
AD56a	FCNV	—	—	300	Ksps	
AD57a	TSAMP	—	3 TAD	—	—	

### 3. Module: 10-bit ADC

When the ADC module is configured for 10-bit operation, the specifications in the data sheet are not met for operation above 500 Ksps.

For 500 Ksps, the module meets specifications except for Gain and Offset parameters AD23bb and AD24bb.

For 600 Ksps operation, the module specifications are shown in Table 2.

#### Work around

None. Future versions of the silicon will support the ADC performance stated in the data sheet.

**TABLE 2: 600 KSPS OPERATION**

Param No.	Symbol	Min	Typ	Max	Units	Conditions
AD17	RIN	—	—	200	Ohm	10-bit
<b>ADC Accuracy – Measurements taken with External VREF+/VREF-</b>						
AD20b	Nr	—	10 bits	—	Bits	
AD21b	INL	-2	—	2	LSB	
AD22b	DNL	-1.5	—	2	LSB	
AD23b	GERR	1	3	6	LSB	
AD24b	EOFF	1	2	5	LSB	
<b>ADC Accuracy – Measurements taken with Internal VREF+/VREF-</b>						
AD21bb	INL	-2	—	2	LSB	
AD22bb	DNL	-1.5	—	2	LSB	
AD23bb	GERR	1	6	12	LSB	
AD24bb	EOFF	2	5	10	LSB	
<b>Dynamic Performance</b>						
AD33b	FNYQ	—	—	300	KHz	
AD34b	ENOB	8.5	9.7	9.8	Bits	
<b>ADC Conversion Rate</b>						
AD56b	FCNV	—	—	600	Ksps	
AD57b	TSAMP	—	3 TAD	—	—	

### 4. Module: DMA Module: Interaction with EXCH Instruction

The EXCH instruction does not execute correctly when either of the two operands is numerically equal to the address of any of the DMAC SFRs for this revision of silicon.

#### Work around

If writing source code in assembly, the recommended fix is to replace:

EXCH Wsource, Wdestination

with:

```
PUSH Wdestination  
MOV Wsource, Wdestination  
POP Wsource
```

If using the MPLAB C30 C compiler, check the disassembly listing ([View>Disassembly Listing](#)) for the EXCH instruction. If used, make sure the operands are not equivalent to the DMA SFRs' addresses.

## 5. Module: DISI Instruction

When a user executes a `DISI #7`, for example, this will disable interrupts for  $7 + 1$  cycles ( $7 +$  the `DISI` instruction itself). In this case, the `DISI` instruction uses a counter which counts down from 7 to 0. The counter is loaded with 7 at the end of the `DISI` instruction.

If the user code executes another `DISI` on the instruction cycle where the `DISI` counter has become zero, the new `DISI` count is loaded, but the `DISI` state machine does not properly re-engage and continue to disable interrupts. At this point, all interrupts are enabled. The next time the user code executes a `DISI` instruction, the feature will act normally and block interrupts.

In summary, it is only when a `DISI` execution is coincident with the current `DISI` count = 0, that the issue occurs. Executing a `DISI` instruction before the `DISI` counter reaches zero will not produce this error. In this case, the `DISI` counter is loaded with the new value, and interrupts remain disabled until the counter becomes zero.

### Work around

When executing multiple `DISI` instructions within the source code, make sure that subsequent `DISI` instructions have at least one instruction cycle between the time that the `DISI` counter decrements to zero and the next `DISI` instruction. Alternatively, make sure that subsequent `DISI` instructions are called before the `DISI` counter decrements to zero.

## 6. Module: Motor Control PWM

Devices in the motor control family have a glitch in the `PWMxL` signal under certain conditions. The glitch is a brief high pulse during the low portion of the duty cycle. This error occurs when the module is configured in Single-Shot mode (`PTMOD<1:0> = 01`) with complementary output. It also occurs when resuming from a Fault condition in Free-Running mode (`PTMOD<1:0> = 00`) with complementary output.

### Work around

None.

## 7. Module: Output Compare Module

A glitch will be produced on an output compare pin under the following conditions:

- The user software initially drives the I/O pin high using the output compare module or a write to the associated PORT register.
- The output compare module is configured and enabled to drive the pin low at some later time (`OCxCON = 0x0002` or `OCxCON = 0x0003`).

When these events occur, the output compare module will drive the pin low for one instruction cycle (`TCY`) after the module is enabled.

### Work around

None. However, the user may use a timer interrupt and write to the associated PORT register to control the pin manually.

## 8. Module: Output Compare Module in PWM Mode

The output compare module will miss a compare event when the current duty cycle register (`OCxRS`) value is `0x0000` (0% duty cycle) and the `OCxRS` register is updated with a value of `0x0001`. The compare event is missed only the first time a value of `0x0001` is written to `OCxRS`, and the PWM output remains low for one PWM period. Subsequent PWM high and low times occur as expected.

### Work around

None. If the current `OCxRS` register value is `0x0000`, avoid writing a value of `0x0001` to `OCxRS`. Instead, write a value of `0x0002`; however, in this case the duty cycle will be slightly different from the desired value.

## 9. Module: SPI Module in Frame Master Mode

The SPI module will fail to generate frame synchronization pulses when configured in the Frame Master mode (FRMEN = 1, SPIFSD = 0). However, the module functions correctly in Frame Slave mode.

### Work around

If DMA is not being used, manually drive the SSx pin ( $x = 1$  or  $2$ ) high using the associated PORT register, and then drive it low after the required 1 bit-time pulse width. This operation needs to be performed when the transmit buffer is written.

If DMA is being used, and if no other peripheral modules are using DMA transfers, use a timer interrupt to periodically generate the frame synchronization pulse (using the method described above) after every 8 or 16 bit periods (depending on the data word size, configured using the MODE16 bit).

## 10. Module: SPI Module in Slave Select Mode

The SPI module Slave Select functionality (enabled by setting SSEN = 1) will not function correctly. Whether the SSx pin ( $x = 1$  or  $2$ ) is high or low, the SPI data transfer will be completed and an interrupt will be generated.

### Work around

If DMA is not being used, manually poll the SSx pin state in the SPI interrupt by reading the associated LAT bit:

- If the LAT bit is '0', then perform the required data read/write.
- If the LAT bit is '1', then clear the SPI interrupt flag (SPIxIF), perform a dummy read of the SPIxBUF register, and return from the Interrupt Service Routine.

If DMA is being used, there is no work around.

## 11. Module: SPI Module

The SMP bit (SPIxCON1<9>, where  $x = 1$  or  $2$ ) does not have any effect when the SPI module is configured for a 1:1 prescale factor in Master mode. In this mode, whether the SMP bit is set or cleared, the data is always sampled at the end of data output time.

### Work around

If sampling at the middle of data output time is required, then configure the SPI module to use a clock prescale factor other than 1:1 using the PPRE<1:0> and SPRE<2:0> bits in the SPIxCON1 register.

## 12. Module: ECAN Module

If multiple ECAN transmit buffers are queued for transmission (multiple TXREQ bits are set to '1' simultaneously), then the message transmissions from the enabled buffers may interfere with one another. As a result, incorrect ID and data transmissions will occur intermittently.

### Work around

Enable only one transmit buffer for transmission at any given time. In the user application, this can be ensured by checking that all other TXREQn bits are clear before setting the TXREQn bit corresponding to the buffer that is to be transmitted.

## 13. Module: ECAN Module

Under specific conditions, the first five bits of a transmitted identifier may not match the value in the transmit buffer SID. If the ECAN module detects a Start-of-Frame (SOF) in the third bit of interframe space and if a message to be transmitted is pending, the first five bits of the transmitted identifier may be corrupted.

### Work around

None.

## 14. Module: ECAN Module Loopback Mode

The ECAN module (ECAN1 or ECAN2) does not function correctly in Loopback mode.

### Work around

Do not use Loopback mode.

## 15. Module: I<sup>2</sup>C Module

The Bus Collision Status bit (BCL) does not get set when a bus collision occurs during a Restart or Stop event. However, the BCL bit gets set when a bus collision occurs during a Start event.

### Work around

None.

## 16. Module: INT0, ADC and Sleep/Idle Mode

ADC event triggers from the INT0 pin will not wake-up the device from Sleep or Idle mode if the SMPI bits are non-zero. This means that if the ADC is configured to generate an interrupt after a certain number of INT0 triggered conversions, the ADC conversions will not be triggered and the device will remain in Sleep. The ADC will perform conversions and wake-up the device only if it is configured to generate an interrupt after each INT0 triggered conversion (SMPI<3:0> = 0000).

### Work around

None. If ADC event trigger from the INT0 pin is required, initialize SMPI<3:0> to '0000' (interrupt on every conversion).

## 17. Module: Doze Mode and Traps

The address error trap, stack error trap, math error trap and DMA error trap will not wake-up a device from Doze mode.

### Work around

None.

## 18. Module: JTAG Programming

JTAG programming does not work.

### Work around

None.

## APPENDIX A: REVISION HISTORY

### Revision A (6/2006)

- Initial release of the document.

### Revision B (12/2006)

- Added errata 7, 8, 9, 10, 11, 12, 13, 14, 15, 16 and 17.

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AmpLab, FilterLab, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, Mindi, MiWi, MPASM, MPLIB, MPLINK, PICtail, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rFLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2006, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.



Printed on recycled paper.

---

**QUALITY MANAGEMENT SYSTEM  
CERTIFIED BY DNV  
=ISO/TS 16949:2002=**

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona, Gresham, Oregon and Mountain View, California. The Company's quality system processes and procedures are for its PIC® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



# MICROCHIP

## WORLDWIDE SALES AND SERVICE

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**

Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**

Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**

Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**

Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**

Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Kokomo**

Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

**Los Angeles**

Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**

Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**

Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Habour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Fuzhou**  
Tel: 86-591-8750-3506  
Fax: 86-591-8750-3521

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Shunde**  
Tel: 86-757-2839-5507  
Fax: 86-757-2839-5571

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7250  
Fax: 86-29-8833-7256

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Yokohama**  
Tel: 81-45-471-6166  
Fax: 81-45-471-6122

**Korea - Gumi**  
Tel: 82-54-473-4301  
Fax: 82-54-473-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Penang**  
Tel: 60-4-646-8870  
Fax: 60-4-646-5086

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-572-9526  
Fax: 886-3-572-6459

**Taiwan - Kaohsiung**  
Tel: 886-7-536-4818  
Fax: 886-7-536-4803

**Taiwan - Taipei**  
Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820